


Field Termination Plug User Guide

Tool Free



Conductive cloth
50mm
10


选配件

Wiring Configurations

T568A	1 White Green	2 Green	3 White Orange	4 Blue	5 White Blue	6 Orange	7 White Brown	8 Brown
T568B	1 White Orange	2 Orange	3 White Green	4 Blue	5 White Blue	6 Green	7 White Brown	8 Brown


	Solid	Stranded	Cable(O.D.)
C8	22~24AWG	22~24AWG	7.0~9.0mm
C6A/C7	23~26AWG	23~26AWG	6.5~9.0mm

①




Boot
Tightening Sleeve
Boot
Boot
(8.0~9.0)Cable (6.5~8.0)Cable

②




40mm
10mm
OR
40mm
10mm
U/FTP F/UTP S/FTP

③




10mm
40mm
Conductive cloth

④




Cable

⑤




5~8mm

⑥




0.2~0.3mm
Align

⑦




Close

⑧ a 不带转角



Tightening Sleeve
Screw (8.0~9.0)Cable
Screw (6.5~8.0)Cable


⑨ a 不带转角




MAX 0.5mm

+


选配件



⑧ b 带转角



⑨ b 带转角可按4个方向调整



a. 向下
a. 向右
a. 向上
a. 向左